



Guida all'aggiornamento firmware su TPLINK EX510

1. Configurazione

Procedere andando nella sezione "System Tools" → "Firmware Upgrade" e assicurarsi della versione del dispositivo, V1 e V2, una volta identificata la versione, recatevi sul seguente link.

<https://www.tp-link.com/it/support/download/ex510-pro/>

E scaricate l'ultimo firmware per la versione corretta del vostro router, attendere il riavvio e il firmware è aggiornato.

The screenshot shows the TP-Link web interface for an EX510 Pro router. The left sidebar has a yellow highlight on 'System Tools' and 'Firmware Upgrade'. The main content area is under the 'Advanced' tab. It displays 'Device Information' with the current firmware version '0.4.0 3.0.0 v6084.0 Build 221124 Rel.40256n' and hardware version 'EX510 Pro v1.0 00000000'. Below this is the 'Online Upgrade' section with a table showing the latest firmware version. There are 'Upgrade' and 'Check for Upgrades' buttons. The 'Local Upgrade' section has a table for selecting a device to upgrade. At the bottom, there is a 'New firmware file:' field with 'Browse' and 'Upgrade' buttons.

Device Information

Firmware Version: 0.4.0 3.0.0 v6084.0 Build 221124 Rel.40256n

Hardware Version: EX510 Pro v1.0 00000000

Online Upgrade

ID	Device Name	Model Name	MAC Address	Firmware Version	Latest Firmware
1	EX510 Pro_7803	EX510 Pro	9C:53:22:71:78:03	0.4.0 3.0.0 v6084.0 Build 221124 Rel.40256n	--

Local Upgrade

-	ID	Device Name	Model Name	MAC Address	Firmware Version
☐	1	EX510 Pro_7803	EX510 Pro	9C:53:22:71:78:03	0.4.0 3.0.0 v6084.0 Build 221124 Rel.40256n

New firmware file: **Browse** **Upgrade**